


# Release Notes

## Intel® Wireless Bluetooth® 21.10.1



Package Version and Supported Operating Systems	21.10.1 for: Microsoft Windows® 10 Microsoft Windows® 7
---	---

### Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10	Windows® 7
Intel® Wi-Fi 6 AX200	21.10.1.1 <sup>1</sup>	N/A
Intel® Wireless-AC 9560 <sup>1</sup>		
Intel® Wireless-AC 9462 <sup>1</sup>		
Intel® Wireless-AC 9461 <sup>1</sup>		
Intel® Wireless-AC 9260 <sup>1</sup>		
Intel® Dual Band Wireless-AC 8265	20.100.5.1	20.90.5.1
Intel® Dual Band Wireless-AC 8260		
Intel® Dual Band Wireless-AC 3168		
Intel® Dual Band Wireless-AC 3165		
Intel® Wireless 7265 Family		
Intel® Dual Band Wireless-AC 3160		
Intel® Wireless 7260 Family		

<sup>1</sup>64 Bit only

### Key Issues Fixed and Changes on package version 21.10.1

Description of Key Issue	OS
Error message “Bluetooth file transfer not complete” shown after Bluetooth OPP file transfer attempt.	Windows 10®
Bluetooth device gets Yellow Bang in Device Manager, after resuming from Hibernation or shutdown with airplane mode on.	Windows 10®
Bluetooth LE mouse connection is intermittent when PC is connected to 2.4GHz Access Point channel via WiFi at the same time	Windows 10®
Bluetooth may stop functioning in some systems after ~20 minutes in idle state.	Windows 10®
General stability improvements and optimizations.	All

Note: Key issues fixed in the OS indicated in the table above.



## **Legal Notices**

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](http://intel.com).

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© February 2018 Intel Corporation.

